



Vehicle History Report



01/12/2024

AUDI A4

Located in: **Italy**

Vehicle reference:

WAUZZZ8E76A084299

Body type: **Sedan**

Gearbox type: **Automatic**

Drive: **Front**

Fuel type: **Diesel**

Engine size: **1968 cm3**

Engine power: **103 kW / 140 hp**



Accident reported



Number of odometer readings: 4



Number of inspection records: 4



Total number of records: 8

Report created on:

01/12/2024 at 09:16:40



Scan QR code for [current version](#) (available until: 31/12/2024)

Quick Check

Damage

This vehicle has had an accident. Have it inspected by a mechanic before purchasing.

Accident

Import

Not a private import

No issues reported

Vincoli

No administrative detention or other liens reported for this vehicle (source ACI, information received on 01/12/2024). [What is a "Vincoli"](#)

No issues reported

Ipoteca


No "Ipoteca" reported for this vehicle (source ACI, information received on 01/12/2024). [What is an "Ipoteca"](#)

No issues reported

This history is based on data reported to us and available upon request. Gaps and errors cannot be excluded. Use CARFAX in combination with a test drive and inspection by experts. We process personal data only in accordance with applicable regulations. Conclusions on owners are not possible at any time.

Damage Overview

24/03/2021 Damage reported



Damaged area:

- Front
- Right
- Right front
- Right rear

Reported on:

24/03/2021

Reported in:


Italy

Severity scale:


Minor

Damage type/cause:

Vandalism



01/02/2023 Damage reported



Damage type/cause:

Collision with another vehicle

Reported on:

01/02/2023

Reported in:

Italy

Mileage Check

Date | Mileage
23/09/2024 | 39 131 km



No issues indicated: The reported odometer readings have a logical progression. There are no indications of manipulation. Unfortunately, we cannot guarantee this, so we always recommend critically questioning the odometer readings, e.g. on signs of wear, the number of oil changes, or the average kilometers driven per year.

Highlights

Odometer

39131

Last reported: 23/09/2024

Vehicle age

years | months
19 | **2**

First registration date: 16/09/2005

Inspections



Latest inspection:
23/09/2024

Inspection due date: 30/09/2026

Owners **BETA****Owner 1 in Italy**

Purchase year:	2005
Length of use:	19 years 1 month
Type of owner:	Private individual
Damage reported on:	01/02/2023, 24/03/2021

Owner 2 in Italy

Purchase year:	2024
Type of owner:	Private individual

History information

Date	Mileage	Event
16/09/2005		Registered in Italy New owner reported Owner type: private individual
22/06/2018	23 000 km	Inspected in Italy
08/06/2020	28 600 km	Inspected in Italy
24/03/2021		Damage reported in Italy caused by vandalism
27/06/2022	36 000 km	Inspected in Italy
01/02/2023		Accident reported in Italy
23/09/2024	39 131 km	Inspected in Italy Inspection valid until 30/09/2026
28/10/2024		New owner reported Owner type: private individual

Based on data reviewed from 22 countries in Europe and North America

Technical details	
Environment and consumption	
Fuel type	Diesel
EU emission standard	Euro 4
Weight	
Curb weight	1 615 kg
Max payload	405 kg
Gross vehicle weight	2 020 kg
Dimensions	
Length	4 586 mm
Width	1 772 mm
Wheelbase	2 655 mm
Other information	
European vehicle category	M1
EU standard code	e1*2001/116*0151
Number of doors	4
Number of seats	5

CARFAX Glossary

Accident

This vehicle has had an accident. You will want to know the type, severity, impact location, whether or not airbags were deployed, etc. We recommend that you obtain a thorough inspection by an independent mechanic before purchasing.

Inspections

Periodic examination of a vehicle to ensure compliance with road worthiness, emissions and safety requirements.

Ipoteca

"Ipoteca" is a security in favor of a creditor over a vehicle belonging to the debtor: creditors can protect themselves by taking out an "Ipoteca" on the vehicle. "Ipoteca" creates a lien on the vehicle without preventing the owner from using and disposing/selling the vehicle. The mortgage, once registered, follows the vehicle until the secured claim is extinguished, even if there are subsequent transfers of ownership.

Number of odometer readings

The periodic mileage as reported to CARFAX. A greater number of odometer readings increases the likelihood of correct mileage.

Number of records

A CARFAX record refers to a specific incidence and date in the history of the vehicle. Please note that the history of younger vehicles tends to have fewer entries. CARFAX continuously works on getting more data sources and historical information in order to enrich the report

Odometer

The number of kilometers displayed on the most recent odometer reading.

Quick Check

A snapshot of the information CARFAX has abstracted from our extensive database to determine whether a vehicle has been reported stolen, reported scrapped, publicly imported or ever used for non-personal purposes. This summary is based upon all the information supplied to CARFAX from various sources. Additional information about this vehicle, including these potential problems, may exist and may not have been reported to CARFAX.

Severity scale - Minor

Generally, minor damage is cosmetic (including dents or scratches), may only require reconditioning, and typically does not compromise a vehicle's operation and/or safety.

Severity scale - Moderate

Moderate damage may affect multiple components of the vehicle and may impair the vehicle's operation and/or safety.

Severity scale - Severe

Severe damage usually affects multiple components of the vehicle and is likely to compromise the vehicle's operation and/or safety.

Vehicle reference

User-provided value to identify the vehicle during the CARFAX Vehicle History Report retrieval process and to confirm vehicle identity on the report itself.

Vincoli

There is an administrative impoundment or upcoming seizure, what means that the car may not be used or sold. Reasons for a seizure, can be drunk driving, not paid taxes or no valid insurance.