

CARFAX Vehicle History Report



PEUGEOT 3008

Located in: Italy Vehicle reference:

VF30URHHAAS268402

Body type: SUV/MPV Gearbox type: Automatic Drive: Front Fuel type: Diesel Engine size: 1997 cm3 Engine power: 120 kW / 163 hp



Minor damage reported



Number of odometer readings: 4



Number of inspection records: 5



Total number of records: 8

Report created on: 04/04/2025 at 14:39:08



Scan QR code for $\underline{\text{\bf current version}}$ (available until: 14/04/2025)

Quick Check

This vehicle has had a damage. Please check with the seller if it has been repaired in the meanwhile, or have it inspected by a mechanic before purchasing.



Damage

Import

Not a private import



No issues reported

No administrative detention or other liens reported for this vehicle (source ACI, information received on 15/03/2025). What is a "Vincoli"



No issues reported

Ipoteca

No "Ipoteca" reported for this vehicle (source ACI, information received on 15/03/2025). What is an "Ipoteca"




No issues reported

This history is based on data reported to us and available upon request. Gaps and errors cannot be excluded. Use CARFAX in combination with a test drive and inspection by experts. We process personal data only in accordance with applicable regulations. Conclusions on owners are not possible at any time.

Damage Overview

22/09/2014 Damage reported



Damaged area:

Front

Severity scale:

Minor

Damage type/cause: Not available Reported on: 22/09/2014

Reported in: Italy

Mileage Check


Last odometer reading

75962 km

Reported on: 24/02/2025

Average mileage

5330 km/year





No issues indicated: The reported odometer readings have a logical progression. There are no indications of manipulation. Unfortunately, we cannot guarantee this, so we always recommend critically questioning the odometer readings, e.g. on signs of wear, the number of oil changes, or the average kilometers driven per year.

Owners BETA	
Owner 1 in Italy	
Purchase year:	2010
Length of use:	14 years 4 months
Type of owner:	Private individual
Damage reported on:	22/09/2014
Owner 2 in Italy	
Purchase year:	2025
Type of owner:	Commercial business

History information		
Date	Mileage	Event
04/11/2010		Registered in Italy New owner reported Owner type: private individual
22/09/2014		Damage reported in Italy
30/10/2014		Inspected in Italy Inspection passed
27/10/2016	56 899 km	Inspected in Italy Inspection passed
18/10/2018	66 009 km	Inspected in Italy Inspection passed
21/10/2020	73 738 km	Inspected in Italy
24/02/2025	75 962 km	Inspected in Italy Inspection valid until 28/02/2027
13/03/2025		New owner reported Owner type: commercial
Based on data reviewed from 22 countries in Europe and North America		

Technical details	
Environment and consumption	
Fuel type	Diesel
EU emission standard	Euro 5
Weight	
Curb weight	1 614 kg
Max payload	486 kg
Gross vehicle weight	2 100 kg
Dimensions	
Length	4365 mm
Width	1 837 mm
Wheelbase	2 613 mm
Other information	
European vehicle category	M1
EU standard code	e2*2001/116*0377*04
Number of doors	5
Number of seats	5

CARFAX Glossary

Average Mileage

Average Mileage is not the actual odometer reading for this car, but an estimate of how many kilometers an average car of this make, model, fuel type and age would be expected to have if used solely for personal use. The actual mileage for this particular car will indicate if it has been driven more or less than average and may be a factor to help you determine its value

Damage

Damage can be a result of many different types of events. Examples include contact with objects (other vehicles, trees, traffic signs, road debris, etc), vandalism, fire, flood, or other weather-related events. CARFAX recommends that you have this vehicle inspected by a qualified mechanic.

Inspections

Periodic examination of a vehicle to ensure compliance with road worthiness, emissions and safety requirements.

Ipoteca

"Ipoteca" is a security in flavor of a creditor over a vehicle belonging to the debtor: creditors can protect themselves by taking out an "Ipoteca" on the vehicle. "Ipoteca" creates a lien on the vehicle without preventing the owner from using and disposing/selling the vehicle. The mortgage, once registered, follows the vehicle until the secured claim is extinguished, even if there are subsequent transfers of ownership.

Number of odometer readings

The periodic mileage as reported to CARFAX. A greater number of odometer readings increases the likelihood of correct mileage.

Number of records

A CARFAX record refers to a specific incidence and date in the history of the vehicle. Please note that the history of younger vehicles tends to have fewer entries. CARFAX continuously works on getting more data sources and historical information in order to enrich the report

Quick Check

A snapshot of the information CARFAX has abstracted from our extensive database to determine whether a vehicle has been reported stolen, reported scrapped, publicly imported or ever used for non-personal purposes. This summary is based upon all the information supplied to CARFAX from various sources. Additional information about this vehicle, including these potential problems, may exist and may not have been reported to CARFAX.

Severity scale - Minor

Generally, minor damage is cosmetic (including dents or scratches), may only require reconditioning, and typically does not compromise a vehicle's operation and/or safety.

Severity scale - Moderate

Moderate damage may affect multiple components of the vehicle and may impair the vehicle's operation and/or safety.

Severity scale - Severe

Severe damage usually affects multiple components of the vehicle and is likely to compromise the vehicle's operation and/or safety.

Vohiolo reference

User-provided value to identify the vehicle during the CARFAX Vehicle History Report retrieval process and to confirm vehicle identity on the report itself.

Vincoli

There is an administrative impoundment or upcoming seizure, what means that the car may not be used or sold. Reasons for a seizure, can be drunk driving, not paid taxes or no valid insurance.