



Vehicle History Report

PEUGEOT 208

Vehicle reference:

VF3CCBHY6FT206435

Body type:

Hatchback

Gearbox type:

Manual

Report created on:

25/07/2025 at 17:10:18

Engine size:

1560 cm³

Fuel type:

Diesel



Combustion engine power:

73 kW / 99 hp

Drive:

Front

Scan QR code for [current version](#)

Located in Italy



Vehicle age

**9 years
8 months**

1-Owner vehicle



How to use this report

This history is based on data reported to us and available upon request. Gaps and errors cannot be excluded. Use CARFAX in combination with a test drive and inspection by experts. We process personal data only in accordance with applicable regulations. Conclusions on owners are not possible at any time.



Quick Check

Damage

This vehicle has had an accident. Have it inspected by a mechanic before purchasing.

● Accident


Import

Not a private import

● No issues reported

Damage Overview

29/01/2025 Damage reported



Damaged area:

- Rear
- Right
- Right rear

Reported on:

29/01/2025

Reported in:

Italy

Severity scale:

Minor

Damage type/cause:

Collision with another vehicle


SEVERITY SCALE



Mileage Check

Date
13/01/2020

Mileage
2 973 km



No issues indicated: The reported odometer readings have a logical progression. There are no indications of manipulation. Unfortunately, we cannot guarantee this, so we always recommend critically questioning the odometer readings, e.g. on signs of wear, the number of oil changes, or the average kilometers driven per year.

**Owner 1 in Italy**

Purchase year:	2015
Length of use:	9 years 8 months
Damage reported on:	29/01/2025

History information

Date	Mileage	Event
06/11/2015		Registered in Italy New owner reported
13/01/2020	2 973 km	Inspected in Italy
29/01/2025		Accident reported in Italy

Based on data reviewed from 22 countries in Europe and North America

Technical details	
Engine and performance	
Fuel type	Diesel
Combustion engine power	73 kW / 99 hp
Environment and consumption	
EU emission standard	Euro 6
Weight	
Curb weight	1 165 kg
Max payload	515 kg
Gross vehicle weight	1 680 kg
Dimensions	
Length	3 973 mm
Width	1 739 mm
Wheelbase	2 538 mm
Other information	
European vehicle category	M1
EU standard code	e2*2007/46*0070*26
Number of doors	5
Number of seats	5

CARFAX Glossary

1-Owner vehicle

1-Owner vehicle has been only used by one owner and consequently comes with the advantage that only one owner is responsible for its use

Number of records

A CARFAX record refers to a specific incidence and date in the history of the vehicle. Please note that the history of younger vehicles tends to have fewer entries. CARFAX continuously works on getting more data sources and historical information in order to enrich the report

Quick Check

A snapshot of the information CARFAX has abstracted from our extensive database to determine whether a vehicle has been reported stolen, reported scrapped, publicly imported or ever used for non-personal purposes. This summary is based upon all the information supplied to CARFAX from various sources. Additional information about this vehicle, including these potential problems, may exist and may not have been reported to CARFAX.

Severity scale - Minor

Generally, minor damage is cosmetic (including dents or scratches), may only require reconditioning, and typically does not compromise a vehicle's operation and/or safety.

Severity scale - Moderate

Moderate damage may affect multiple components of the vehicle and may impair the vehicle's operation and/or safety.

Severity scale - Severe

Severe damage usually affects multiple components of the vehicle and is likely to compromise the vehicle's operation and/or safety.