



Vehicle History Report

HONDA CR-V

Vehicle reference:

SHSRE6750BU007624

Body type:
SUV/MPV

Gearbox type:
Manual

Engine size:
2199 cm³

Fuel type:
Diesel

Engine power:
110 kW / 150 hp

Drive:
AWD

Report created on:

11/07/2025 at 15:40:31



Scan QR code for [current version](#)

Located in Italy



Vehicle age

**14 years
2 months**

How to use this report

This history is based on data reported to us and available upon request. Gaps and errors cannot be excluded. Use CARFAX in combination with a test drive and inspection by experts. We process personal data only in accordance with applicable regulations. Conclusions on owners are not possible at any time.



Quick Check

Damage

No damage reported to CARFAX

No issues reported

Import

Not a private import

No issues reported

Damage Overview



No damage reported: There has been no damage reported for this vehicle

Mileage Check

Last odometer reading

88 367 km


Reported on: 09/04/2025

Average mileage

6 349 km/year

Average mileage for similar cars

16 032 km/year



No issues indicated: The reported odometer readings have a logical progression. There are no indications of manipulation. Unfortunately, we cannot guarantee this, so we always recommend critically questioning the odometer readings, e.g. on signs of wear, the number of oil changes, or the average kilometers driven per year.

**Owner(s) in Italy**

Purchase year: **2011**

There is no more information available about one or more consecutive owners.

Owner(s) in Italy

Purchase year: **2011**

There is no more information available about one or more consecutive owners.

History information

Date	Mileage	Event
29/04/2011		Registered in Italy
02/11/2011		New owner reported
14/04/2015		Inspected in Italy Inspection passed
13/04/2017	54 297 km	Inspected in Italy Inspection passed
05/04/2019	72 426 km	Inspected in Italy Inspection passed
01/04/2021	81 722 km	Inspected in Italy Inspection passed
03/04/2023	84 330 km	Inspected in Italy Inspection passed

Date	Mileage	Event
09/04/2025	88 367 km	Inspected in Italy Inspection passed Inspection valid until 09/04/2027
Based on data reviewed from 22 countries in Europe and North America		

Technical details	
Environment and consumption	
Fuel type	Diesel
EU emission standard	Euro 5
Weight	
Curb weight	1 722 kg
Max payload	438 kg
Gross vehicle weight	2 160 kg
Dimensions	
Length	4 570 mm
Width	1 870 mm
Wheelbase	2 630 mm
Other information	
European vehicle category	M1
EU standard code	e11*2001/116*0302*04
Number of doors	5
Number of seats	5

CARFAX Glossary

Average Mileage

Average Mileage is not the actual odometer reading for this car, but an estimate of how many kilometers an average car of this make, model, fuel type and age would be expected to have if used solely for personal use. The actual mileage for this particular car will indicate if it has been driven more or less than average and may be a factor to help you determine its value

Number of records

A CARFAX record refers to a specific incidence and date in the history of the vehicle. Please note that the history of younger vehicles tends to have fewer entries. CARFAX continuously works on getting more data sources and historical information in order to enrich the report

Quick Check

A snapshot of the information CARFAX has abstracted from our extensive database to determine whether a vehicle has been reported stolen, reported scrapped, publicly imported or ever used for non-personal purposes. This summary is based upon all the information supplied to CARFAX from various sources. Additional information about this vehicle, including these potential problems, may exist and may not have been reported to CARFAX.